



WALL SOCKET
3 PHASE MAINS
SUPPLY
NEEDS TO BE
5 PIN 32AMP
OUTLET

WE HIRE SURFACE PREPARATION EQUIPMENT

CONNECTING 3 PHASE TRANSFORMER TO MAINS FOR USE WITH RANGE OF 110V FLOOR MACHINE AND DUST CONTROL UNIT

32AMP 3PHASE
5PIN LEAD
15MTRS LONG



10KVA 3PHASE SITE
TRANSFORMER FITTED WITH
32AMP 3 PHASE 5 PIN PLUG



CONNECT NO MORE THAN TWO
32AMP 4MM 110V LEADS INTO ONE
OF THE 32A SOCKETS



CONNECT NO MORE THAN TWO
32AMP 4MM 110V LEADS INTO ONE
OF THE 32A SOCKETS



CONNECT YOUR APPLIANCE TO NO MORE THAN
TWO EXTENSION LEADS



REMOVE HOSE FROM DRUM , CONNECT UP TO APPLIANCE



or



or

